Date: 5-4-11 Time: 9:30 am Location: 103 European
Please Circle Appropriate Action: New Line Installation/ Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 2" Gelu Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) ¹ Time Water Main Valved Off (positive pressure removed): am / pm Nature of Leak or Break: Smell hole in 2" Galu main
Were State approved or AWWA Standards Followed: (YES) NO) Detailed summary of repair procedure used (Use back of page if needed): Repaired with Full Circle Band
Was water main contaminated during the repair process? (YES / NO) Blenched Brid Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YESNO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Sec Photos
Rev 01-21-09 Adam - Reed - Kin - Dier