

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 2-23-11

Time 2:00 p.m.

Location 1235 Airport Rd

Case # [blank] Appropriate Action New Line Installation Line Repair Service Line

NEW LINE INSTALLATION

Were State approved or AWWA Standards Followed (YES NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

COPY

2-25-11

J

Monitor Residual Prior to Initial Flush

Date Time of Initial Flush

Length of Time of Initial

Flush

Chlorine Residual after Flush

Water Supply WSI Project Number

FOR LINE REPAIRS

Interruption of Water Service YES ☒ NO Number of Customers Affected 1

Main Size 6" PUC Repaired Under Pressure YES ☒ NO

Was partially or fully de-watered mains

Was positive pressure maintained while a trench was opened and area cleaned YES ☒ NO

Time Water Main Valved Off (positive pressure removed) am pm

Nature of Leak or Break

leaking copper service

Were State approved or AWWA Standards Followed YES ☒ NO

Detailed summary of repair procedure used (Use back of page if needed)

Replaced copper service and saddle

Was water main contaminated during the repair process? YES ☒ NO Flushed line

Amount of Time Line Flushed
Residual mg/L

Minutes

Ending Chlorine 2.20

Bacteriological Sample Collected YES NO

Results**

**Attach copy of results to record

Date Time Water Main Returned to Service

am pm

Additional Comments

See Photos

hot saddle w/ Backhoe, replaced while hot.

6 GPM leak

Adam Kim
Bell

COPY