FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 12-28-11 Time: 10:45 Location: 156 Gent 37
Please Circle Appropriate Action: New Line Installation, Line Repair Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 2" Gelv Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YEST NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: hole in 2" Golv
Were State approved or AWWA Standards Followed: (YES NO) Detailed summary of repair procedure used (Use back of page if needed): Repaired
Was water main contaminated during the repair process? (YES / NO) Disinfection Procedure / Calculations (Use back of page if needed): Contaminated during the repair process? (YES / NO)
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YESNO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Sec Photos
Rev 01-21-09

Adan- Bull-Tim - Good leak

V900