10-27-10 Time: 7:00pm. Location: 178 Forest Hills Or.
Conser Circle Appropriate Action. NEW LINE INSTALLATION, LINE REPAIR
NEW LINE INSTALLATION:
State approved or AWWA Standards Followed: (YES / NO) Linear summary of disinfection procedure used (Use back of page if needed)
Chlorine Residual after Flush:
The Supply (WS) Project Number
FOR LINE REPAIRS:
NO Number of Customers Affected
Repaired Under Pressure: YES NO
partially or fully de-watered mains
Vals positive pressure maintained while a trench was opened and area cleaned CYES
e Water Main Valved Off (positive pressure removed): am .pm
Bell Busted on 2" Puc
Note State approved or AWWA Standards Followed (YES)NO) Detailed summary of repair procedure used (Use back of page if needed): Replaced 23" Section of Pipe of bushedbell with 2 - Knock-ons
Was water main contaminated during the repair process? (YES NO) Bearing the contaminated during the repair process? (YES NO) Blackd PIPC and Knock ons
Amount of Time Line Flushed: Minutes Ending Chlorine Hesiacial mg/L
Bacteriological Sample Collected: YES NO Results** "Attach copy of results to record)
Date Time Water Main Returned to Service 20 am pm
Scc Photos

25 GDM leak