Date: 12-1-14 Time: 5700 Location: 1883 31 ROCAZ 31
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 6" Cast Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)  Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break:  Main broken clean into
Were State approved or AWWA Standards Followed: (YE8 / NO) Randed Leak Detailed summary of repair procedure used (Use back of page if needed):
Was water main contaminated during the repair process? (YES (NO) Rleach Band Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YESNO Results**:(**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Sec Photos Big Leak 2 pumps
2 pumps

5'x8' hole

COPY