## FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 12-12-12 Time: 2:45 Location: 310 Spinier
Please Circle Appropriate Action: New Line Installation (Line Repair Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush:  Date / Time of Initial Flush: Length of Time of Initial  Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NO Number of CustomersAffected:
Main Size: 2" Galo Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)  Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break (Pakins Galu tec + coupling
Were State approved or AWWA Standards Followed: (YES) NO)  Detailed summary of repair procedure used (Use back of page if needed):  Removed tec and Straight lined with plastic & 3 Bolt dresser
Was water main contaminated during the repair process? (YES / NO) Bleccled Pipe Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YES NO Results**:  (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Scc Photos Aclan - Jimmy - Bull
Positin Prosum On Both ends
Throttled value down

\*,.

7

9

e en