FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
Date: 11-29-12 Time: 2:45 Pr Location: 227 Hillwood Dr. 6019
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial  Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:  Interruption of Water Service: YESNONumber of CustomersAffected:
Main Size: 6" PUC Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)  'Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break (eoking Scrolic
Were State approved or AWWA Standards Followed: (YES / NO) Reflected with copper Detailed summary of repair procedure used (Use back of page if needed):
Was water main contaminated during the repair process? (YES / NO) Flushed line Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine 2,20 Residual: mg/L
Bacteriological Sample Collected: YES NO Results**:  (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Sec Photos 3 GPM Leak
Adam - Bull - Donnie Justin

V900

82,010,