

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 2-23-11

Time: 9:45 a.m.

Location: 253 Pines Church Rd

Case: ☐ New Line Installation ☐ Line Repair ☒ Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed (YES NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Initial Residual Prior to Initial Flush

Date: Time of Initial Flush

Length of Time of Initial

Flush

Chlorine Residual after Flush

Water supply WS Project Number

FOR LINE REPAIRS

Interruption of Water Service YES ☒ NO Number of Customers Affected 1

Main Size: 4" PVC

Repaired Under Pressure YES NO

Was partially or fully de-watered mains

Was positive pressure maintained while a trench was opened and area cleaned YES ☒ NO

Time Water Main Valved Off (positive pressure removed) am pm

Nature of Leak or Break

Replace Service

Were State approved or AWWA Standards Followed YES ☒ NO

Detailed summary of repair procedure used (Use back of page if needed)

Replaced Plastic w/ copper

Was water main contaminated during the repair process? (YES NO) ☒ Flushed line

Disinfection Procedure Calculations (Use back of page if needed)

Amount of Time Line Flushed
Residual mg/L

1

Minutes

Ending Chlorine 2.20

Bacteriological Sample Collected YES NO

Results**

**Attach copy of results to record

Date: Time Water Main Returned to Service

am pm

Additional Comments

See Photos

4 GPM leak

Adam
Kim
Bull

COPY

2-25-11

J

1000