FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-23-11 Time: 10:00 Location: 303 Lons Dr.						
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line						
NEW LINE INSTALLATION:						
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):						
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:						
Water Supply (WS) Project Number:						
FOR LINE REPAIRS:						
Interruption of Water Service: YES NONumber of CustomersAffected:						
Main Size: 6" PVL Repaired Under Pressure: YES NO						
For partially or fully de-watered mains:						
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) Time Water Main Valved Off (positive pressure removed): am / pm						
Nature of Leak or Break: Legking Blue Mex Service						
Were State approved or AWWA Standards Followed: (YES) NO) Replaced with Detailed summary of repair procedure used (Use back of page if needed): Copper						
Was water main contaminated during the repair process? (YES NO) [=lusked line] Disinfection Procedure / Calculations (Use back of page if needed):						
Amount of Time Line Flushed: Minutes Ending Chlorine 2. 2.0 Residual: mg/L						
Bacteriological Sample Collected: YESNO Results**: (**Attach copy of results to record)						
Date / Time Water Main Returned to Service: am / pm						
Additional Comments: Sec Photos						
8 GPM leak Adam-Daniel-Johnny						

		Ó