

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-22-10 Time: 3:30 p.m. Location: 320 Pecos Loop Rd

Case # and Appropriate Action: New Line Installation Line Repair Service Line

**NEW LINE INSTALLATION**

Were State approved or AWWA Standards Followed (YES NO)
Detailed summary of disinfection procedure used (Use back of page if needed)

Chlorine Residual Prior to Initial Flush
Date Time of Initial Flush Length of Time of Initial Flush
Chlorine Residual after Flush

Water supply WS-Project Number

**FOR LINE REPAIRS**

Interruption of Water Service: YES NO Number of Customers Affected: 1

Main Size: 2" PVC Repaired Under Pressure: YES NO

Was partially or fully de-watered mains

Was positive pressure maintained while a trench was opened and area cleaned? YES

Time Water Main Valved Off (positive pressure removed): am/pm

Nature of Leak or Break: Leaking Blue Max service

Were State approved or AWWA Standards Followed (YES NO)

Detailed summary of repair procedure used (Use back of page if needed)

Replaced leaking Plastic with copper

Was water main contaminated during the repair process? (YES NO) Flushed line
Disinfection Procedure: Calculations (Use back of page if needed)

Amount of Time Line Flushed: 1 Minutes Ending Chlorine: 2.20
Residual: mg/L

Bacteriological Sample Collected: YES NO Results\*\*
\*\*Attach copy of results to record

Date Time Water Main Returned to Service: am/pm

Additional Comments:

