FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
Date 4-29-13 Time: 2:00 pm Location: 3441 Airport Rd
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Main Size: 6" DUC Repaired Under Pressure: YES NO
For partially or fully de-watered mains
Was positive pressure maintained while a trench was opened and area cleaned (YES / NO) 'Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break leaking poly service line
Were State approved or AWWA Standards Followed: (YES) NO) Replaced with Detailed summary of repair procedure used (Use back of page if needed): Copper
Was water main contaminated during the repair process? (YES NO) Flushed line Disinfection Procedure / Calculations (Use back of page if needed): Flushed line
Amount of Time Line Flushed: Minutes Ending Chlorine 2,20 Residual: mg/L
Bacteriological Sample Collected: YESNO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service:am / pm
Additional Comments: Sec Photos
Rev 05-23-06 Adam 6 GPM Leak Donnic Rilly

•

COPY

2014년 - 1917년 - 1918년 1918년 1919년 1919 1919년 - 1919년 19