FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
Date 1-19-11 Time: 3:30Pm Location: 904 Magrace
Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Date / Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
interruption of Water Service: YES NO No Number of Customers Affected:
Main Size 6" Trans. Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (VES)
Time Water Main Valved Off (positive pressure removed): 4 am pro
Nature of Leak or Break: Pulled rip rap rock into main.
Were State approved or AWWA Standards Followed: (YES/NO) Detailed summary of repair procedure used (Use back of page if needed): Our below Pipe & Cleaned area.
Was water main contaminated during the repair process? (YES / NOD Disinfection Procedure / Calculations (Use back of page if needed): Leared Pipe with bleach + put back in Society
Amount of Time Line Flushed: 2 1/2 h-s Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YES NO Results**: "Attach copy of results to record)
Date / Time Water Main Returned to Service: 20 am / pm
Additional Comments: Taylor, Reed Tim Weddle