

# FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 6-11-10 Time: 2:30p Location: Hassler Mill? Highland @  
Lowrie Tidwell's

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

## NEW LINE INSTALLATION:

**COPY**

Jim  
Aden  
Donnie  
Billy  
Taylor

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush: \_\_\_\_\_

Date / Time of Initial Flush: \_\_\_\_\_ Length of Time of Initial

Flush: \_\_\_\_\_ Chlorine Residual after Flush: \_\_\_\_\_

Water Supply (WS) Project Number: \_\_\_\_\_

## FOR LINE REPAIRS:

Interruption of Water Service: YES ☒ NO ☐ Number of Customers Affected: 2

Main Size: 2" Repaired Under Pressure: YES ☐ NO ☒

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) NO

Time Water Main Valved Off (positive pressure removed): 2:30 am / pm

Nature of Leak or Break:

Pulled 2" out of 90° Bell to Bell

Were State approved or AWWA Standards Followed: (YES / NO) NO

Detailed summary of repair procedure used (Use back of page if needed):

Cut Valve off Dug Sump Hole Pumped water 18" Below

Was water main contaminated during the repair process? (YES / NO) NO

Disinfection Procedure / Calculations (Use back of page if needed):

Bleached All Parts 2 x 12 Nipple Brass Brass 90° 2 Bell Rest.

Amount of Time Line Flushed: \_\_\_\_\_ Minutes

Ending Chlorine

Residual: \_\_\_\_\_ mg/L

Bacteriological Sample Collected: YES ☐ NO ☐

Results\*\*: \_\_\_\_\_

(\*\*Attach copy of results to record)

Date / Time Water Main Returned to Service: \_\_\_\_\_ am / pm

Additional Comments:

47.67  
24.98

48 x 48x  
45 sec

COPY