FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 12-21-11 Time: 12:30 Location: Honey suckle La
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION: Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush: Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES VNONumber of CustomersAffected:
Main Size: 2" Poly Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) 1 Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: Butt - fusc leaking - Blowed out
Were State approved or AWWA Standards Followed: (YES) NO) Replaced 13" Section Detailed summary of repair procedure used (Use back of page if needed): with Fusion repair couplings
Was water main contaminated during the repair process? (YES (NO)) Bleached pipe Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes
Bacteriological Sample Collected: YES NO Results**:(**Attach copy of results to record)
Date / Time Water Main Returned to Service: 12-21-11 [15] am (pm)
Additional Comments: See Photos Adem-Donnic-Billy
Rev. 01-21-09

10 GPM leak

Meloo