FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 2-8-11 Time 2:00 P.M. Location Mosnins Dr.
Please Circle Appropriate Action: New Line Installation: Line Repair Service Line
NEW LINE INSTALLATION: Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed)
Chlorine Residual Prior to Initial Flush Date Time of Initial Flush Elush Chlorine Residual after Flush
Nater Supply (WS) Project Number
FOR LINE REPAIRS:
Main Size 1 Blue Matter Service YES NO Number of Customers Affected Main Size 1 Repaired Under Pressure YES NO
For partially or fully de-watered mains
Was positive pressure maintained while a trench was opened and area cleaned (YES). NO! Time Water Main Valved Off (positive pressure removed) am _pm
Nature of Leak or Break hole in 1' Blue Max
Were State approved or AWWA Standards Followed (YE8 NO) Detailed summary of repair procedure used (Use back of page if needed) Replaced Scotion of blue May with copper
Was water main contaminated during the repair process? (YES NO) Bleached copper Disinfection Procedure / Calculations (Use back of page if needed) Bleached copper Hushed line at blow-off
Amount of Time Line Flushed 5 Minutes Ending Chlorine 2.20 Residual mg/L
Bacteriological Sample Collected: YESNO Results** Attach copy of results to record)
Date: Time Water Main Returned to Service: am : pm
Additional Comments had positive pressure - 18" below pipe. Squeezed off upstream side but still had water coming out. Plugged other side into the tap. Tapped off 2" Galu. Car Photos