FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 1-30-14 Time: 1:00 Am. Location: Rosser + Ruitan -3 Please Circle Appropriate Action: New Line Installation (Line Repair) Service Line
Please Circle Appropriate Action: New Line Installation (Line Repair) Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 2" cqs+ Repaired Under Pressure: YES / NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned (YES) NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: Oracked 1" from a bell
Were State approved or AWWA Standards Followed: (VES / NO) Detailed summary of repair procedure used (Use back of page if needed): Blesched Band and parts
Was water main contaminated during the repair process? (YES / NO) Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YES NO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments:
Jeff, Donnie, TJ

ROMEN AND MONORARIAN PART OF THE RESIDENCE OF

LESSANDE DE L'ANDRE DE MANAGEMENT DE L'ANDRE DE SERVICE

Y900

THE STATE OF THE S

in the second of the second of

ji ku Egya segga sa ang mangga sa penagangan tabangga sa Lautha sa garangan sa mangga sa Mandada at Banka sa at sa sa sa