FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR 12-14-10 Time: 11:30 a.m. Location: Sextons Automotive Picase Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR NEW LINE INSTALLATION: Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed) Date. Time of Initial Flush Chlorine Residual after Flush Water Supply (WS) Project Number: FOR LINE REPAIRS: interruption of Water Service: YES NO Number of Customers Affected C Wan Sin 2" Galv Repaired Under Pressure: YES NO her partially or fully de-watered mains: Was positive pressure maintained while a trench was opened and area cleaned (YES Water Main Valved Off (positive pressure removed): am pm

Split in 2" Galve

Were State approved or AWWA Standards Followed (YES NO)
Detailed summary of repair procedure used (Use back of page if needed:

Repaired with band

Was water main contaminated during the repair process? (YES (NO)) Bleached Board Disintection Procedure (Calculations (Use back of page if needed)

Amount of Time Line Flushed: Minutes Ending Chlorine Residual mg/L

Bacteriological Sample Collected: YES NO Results**

"Attach copy of results to record)

Date Time Water Main Returned to Service: 20 am - pm

Sec Photos

Additional Comments

Put ground clamp on pipe and wire for tracing

Ader Derrie-Bul-Kin-Wendell

5 GPM Leak