FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 3-20-12 Time: 6:30 pm Location: Tims line langitudes and
Please Circle Appropriate Action: New Line Installation, Line Repair Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES) NO) 3-26-12 } Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 2191 Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES) NO) Time Water Main Valved Off (positive pressure removed): 7:00 am 16m
Nature of Leak or Break: // PVC Water Mach Were State approved or AWWA Standards Followed: (XE8 LNO)
installed 53" of 2"PVC and 2 Knock ous
Was water main contaminated during the repair process? (YES (NO)) Disinfection Procedure / Calculations (Use back of page if needed): Leacher Kneck on 5 and Julyuc Pipe
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YESNO Results**:(**Attach copy of results to record)
Date / Time Water Main Returned to Service: 3-20-12 8-00 am 16m
Additional Comments:
Rev 01-21-09

