

11-15-10

Time: 6:00

Location: 255 UMA Rd

Please Circle Appropriate Action: NEW LINE INSTALLATION LINE REPAIR**NEW LINE INSTALLATION:**

Were State approved or AWWA Standards Followed? (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Date: Time of Initial Flush:

Chlorine Residual after Flush

Water Supply (WS) Project Number

FOR LINE REPAIRS:Description of Water Service: YES NO Number of Customers Affected: 3Leak Size: 4 Repaired Under Pressure: YES NOpartially or fully de-watered mainsWas positive pressure maintained while a trench was opened and area cleaned? YES

Date:

Time Water Main Valved Off (positive pressure removed): am pm

Location of Leak or Break

Service line had hole in itWere State approved or AWWA Standards Followed? YES / NO

Detailed summary of repair procedure used (Use back of page if needed):

Replaced Blue max with 3/4 copper flushed lineWas water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L

Bacteriological Sample Collected: YES NO Results**

**Attach copy of results to record)

Date: Time Water Main Returned to Service: 20 am pm

Additional Comments

Taylor Fitchugh Reed Coffey hassins 3/4 Blue max had hole in it

