35

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 1-10-14 Time:5:00 P. Location: 3253 Airport Rd
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS: Interruption of Water Service: YES NO Number of CustomersAffected:
Main Size: 6 PVC Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: Replace leakly, Service line
Were State approved or AWWA Standards Followed: (YESTNO) Peplaced: With Detailed summary of repair procedure used (Use back of page if needed):
Was water main contaminated during the repair process? (YES / NO) Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine 2.20 Residual: mg/L
Bacteriological Sample Collected: YES NO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Scc Photos Rev 01-21-09 Aclas Billy 3 GPM Leak
Rev DT-21-09 Adam BILLY
Cook T.T

