FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 12-14-12 Time: 11,00 " Location: 822 Rente Rd
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION: Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YESNONumber of CustomersAffected:
Main Size: 2 PUC Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break (eaking Blue Max Service
Were State approved or AWWA Standards Followed: (YES) NO) Popularity of repair procedure used (Use back of page if needed):
Was water main contaminated during the repair process? (YES /NO) Flushed line Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine 2.20 Residual: mg/L
Bacteriological Sample Collected: YESNO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Sec Photos
Rev 01-21-00 Adam Donnic 4 GPM Leak Boll Brott

Y900