FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 2-25-13 Time: 10:15 Location: Bulleid Food & Enery Hots
Please Circle Appropriate Action: New Line Installation / Line Repair Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 21 Galu Repaired Under Pressure: YESNO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break Split in top of Main
Were State approved or AWWA Standards Followed: (YES) NO) Repaired with Detailed summary of repair procedure used (Use back of page if needed): Band
Was water main contaminated during the repair process? (YES (NO) Bleached Bond Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YESNO Results**: **Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Sce Photes
Rev 01-21-09 Adem Bull Jimny

/900

2

3 2