

## FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

11-29-00

Time: 4:00

Location: Henderson St.

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

## NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Time of Initial Flush:

Chlorine Residual after Flush

Water Supply (WS) Project Number

## FOR LINE REPAIRS:

Disruption of Water Service: YES

NO

Number of Customers Affected

Pipe Size: 3" Trans

Repaired Under Pressure

YES

NO

not partially or fully de-watered mainsWas positive pressure maintained while a trench was opened and area cleaned? YES

Water Main Valved Off (positive pressure removed):

am pm

Cause of Leak or Break

Pipe cracked at Bottom of saddleWere State approved or AWWA Standards Followed: YES NO

Detailed summary of repair procedure used (Use back of page if needed):

Bleached BandWas water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed)

Amount of Time Line Flushed

Minutes

Ending Chlorine

Residual mg/L

Bacteriological Sample Collected: YES

NO

Results\*\*

\*\*Attach copy of results to record)

Date Time Water Main Returned to Service:

20

am pm

Additional Comments

lost Fitchugh Southern Reed CoFox Harmon

