FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 11-8-13 Time:10:30 Location:
Please Circle Appropriate Action: New Line Installation Line Repair Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 3/4 Comor Repaired Under Pressure: YESNO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned (YES / NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: hole in Copper
Were State approved or AWWA Standards Followed (YES) NO) Repair with Detailed summary of repair procedure used (Use back of page if needed):
Was water main contaminated during the repair process? (YES (NO)) Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YES NO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Sec Photos
Additional Comments: Sec Photos Rev D1-21-09 15+ CPM Leak Adam - Donnic-Rilly - Brett
Adan - Donnie - Rilly - Brett

Y900

2.37