FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
Date: 12-17-11 Time: 2:30 Location: Mtn Vice Rd
Please Circle Appropriate Action: New Line Installation Line Repair Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO)
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: <u>4"PUC</u> Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES // NO) ¹ Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: Split in 4" PUC
Were State approved or AWWA Standards Followed: (YES/ NO) Repaired with Bad Detailed summary of repair procedure used (Use back of page if needed):
Was water main contaminated during the repair process? (YES (NO)) Bleached Bend Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YES NO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: See Photos
Adam-Donnic - Daniel 4 GPM leak

V900