## FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 2/11/10 Time: 9:00 Location: South Worden Crown
Please Circle Appropriate Action: New Line Installation Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO)  Detailed summary of disinfection procedure used (Use back of page if needed):  2-17-19
Chlorine Residual Prior to Initial Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 1" PULC Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (¥ES / NO)  Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break:  Note in top 2" PUC.
Were State approved or AWWA Standards Followed: (YES / NO)  Detailed summary of repair procedure used (Use back of page if needed):  Repair z'' band
Was water main contaminated during the repair process? (YES / NO)  Disinfection Procedure / Calculations (Use back of page if needed):  Bleach Bank
Amount of Time Line Flushed: Minutes Ending Chlorine  Residual: mg/L
Bacteriological Sample Collected: YESNO Results**:(**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments:  18 × 24 hole
Rev. 01-21-09

(POP)