

**COST ESTIMATE FOR CONSTRUCTION, RELOCATION, REPAIR, ETC.
OF HUB WATER, GAS, OR SEWER LINES**

Customer: TVA / 1134 Swan Pond Road **Phone No.:** 717-1676
Address: 118 Lakeshore Drive **Account No.:**
Person Making Request or Responsible for Damages Mr. Ron Hutson
(If Other Than the Customer):
Date of Request or Damages: 10/03/2011
Nature of Request or Damages: Disconnected GAS and Water

TOTAL COST OF LABOR	\$238.94
TOTAL COST OF EQUIPMENT	\$126.60
TOTAL COST OF MATERIAL	\$23.53

TOTAL COST OF JOB (Labor+Equipment+Material) \$389.07

Sign: _____ **Date:** _____

Faint, illegible text at the top left of the page.

Faint, illegible text at the top right of the page.

A single line of faint, illegible text spanning the width of the page.

A single line of faint, illegible text spanning the width of the page.

**COST ESTIMATE FOR CONSTRUCTION, RELOCATION, REPAIR, ETC.
OF HUB WATER, GAS, OR SEWER LINES**

Customer: TVA / 1134 Swan Pond Road **Phone No.:** 717-1676

Address: 118 Lakeshore Drive **Account No.:**


Person Making Request or Responsible for Damages Mr. Ron Hu
(If Other Than the Customer):

Date of Request or Damages: 10/03/2011

Nature of Request or Damages: Disconnected GAS and Water

Material:	Description	Units (Ft., #, etc.)	Item Cost	Extended Cost
Cap	1" Brass Cap	1	\$3.17	\$3.17
Lyco	3/4Lyco Plug	1	\$20.36	\$20.36

TOTAL COST OF MATERIAL/ Labor **\$23.53**



2018-2019

2018-2019

2018-2019

THE UNIVERSITY OF CHICAGO

DEPARTMENT OF CHEMISTRY

PHYSICAL CHEMISTRY



Harriman Utility Board

P.O Box 434
Harriman, Tennessee 37748
Gas, Water and Sewer
Manager of G/W/S: Frankie Davis
865-882-3242 .e 227
Fax: 865-882-5127
fdavis@hub-tn.com

Project: TVA Gas & Water Removal

Location: 118 Lakeshore Dr.

Date: 10-3-11

By: Mike Taylor

Sheet # 21 of 72

Notes:

Crews: Taylor, Billy, Harmon, Clank

118 Lakeshore Dr.

2 Hr.

1- 3/4" Lyco Plug	20.36
1- 1" Brass Cap	3.17

- 4- Men
- 1- Backhoe
- 1- Service Truck
- 1- Dump Truck

