

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 4-18-11 Time: 11 AM Location: 1035 & 1023 Bazel Rd.

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

**NEW LINE INSTALLATION:**

*Taylor, Clark, Billy, Herman*

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

**COPY**

4-21-11

Chlorine Residual Prior to Initial Flush: \_\_\_\_\_

Date / Time of Initial Flush: \_\_\_\_\_ Length of Time of Initial

Flush: \_\_\_\_\_ Chlorine Residual after Flush: \_\_\_\_\_

Water Supply (WS) Project Number: \_\_\_\_\_

**FOR LINE REPAIRS:**

Interruption of Water Service: YES \_\_\_ NO \_\_\_ Number of Customers Affected: \_\_\_\_\_

Main Size: \_\_\_\_\_ Repaired Under Pressure: YES \_\_\_ NO \_\_\_

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): \_\_\_\_\_ am / pm

Nature of Leak or Break: \_\_\_\_\_

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: \_\_\_\_\_ Minutes  
Residual: \_\_\_\_\_ mg/L

Ending Chlorine

Bacteriological Sample Collected: YES \_\_\_ NO \_\_\_  
(\*\*Attach copy of results to record)

Results\*\*: \_\_\_\_\_

Date / Time Water Main Returned to Service: \_\_\_\_\_ am / pm

Additional Comments: \_\_\_\_\_

