FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 10-30-12 Time: 2100 p.m. Location: 104 Gattison St GO P
Please Circle Appropriate Action: New Line Installation / Line Repair (Service Line)
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 2" PX Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: leaking Plastic Service line
Were State approved or AWWA Standards Followed: (YES) NO) Replaced with capper Detailed summary of repair procedure used (Use back of page if needed):
Was water main contaminated during the repair process? (YES NO) Flushed line Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine 2,20 Residual: mg/L
Bacteriological Sample Collected: YES NO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Scc Photes
Rev 01-21-00 Adam - Juny - Justin 5 GPM Leak

			Ü
	e.		