

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 2-3-11 Time 10:00 am Location 1104 Comp Austin Rd

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

**NEW LINE INSTALLATION:**

Were State approved or AWWA Standards Followed (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

**COPY**

2-4-11  
J

Chlorine Residual Prior to Initial Flush

Date Time of Initial Flush Length of Time of Initial

Flush Chlorine Residual after Flush

Water Supply (WS) Project Number

**FOR LINE REPAIRS:**

Interruption of Water Service YES ☒ NO Number of Customers Affected 1

Main Size 4" PVC Repaired Under Pressure YES NO

For partially or fully de-watered mains.

Was positive pressure maintained while a trench was opened and area cleaned? (YES) YES NO

Time Water Main Valved Off (positive pressure removed) am pm

Nature of Leak or Break

Replaced service line the Hwy Dept tore out while cleaning ditch

Were State approved or AWWA Standards Followed (YES) YES NO

Detailed summary of repair procedure used (Use back of page if needed)

Replaced with copper

Was water main contaminated during the repair process? (YES) NO

Disinfection Procedure / Calculations (Use back of page if needed)

Flushed line

Amount of Time Line Flushed 1 Minutes  
Residual mg/L

Ending Chlorine 2.20

Bacteriological Sample Collected: YES NO

Results\*\*

(\*\*Attach copy of results to record)

Date Time Water Main Returned to Service am pm

Additional Comments

See Photos

Adam-Reed-Daniel

Hwy Dept broke customer side when pulled HVB service line - we fixed customer side back also

COPY