

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 1-17-11 Time ^{10:00 am} ~~8:00 am~~ Location 110 Love Dr.

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

COPY

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Chlorine Residual Prior to Initial Flush

Date Time of Initial Flush Length of Time of Initial Flush Chlorine Residual after Flush

Water Supply (WS) Project Number

FOR LINE REPAIRS:

Interruption of Water Service: YES NO Number of Customers Affected 1

Main Size 6" PVC Repaired Under Pressure YES NO

For partially or fully de-watered mains

Was positive pressure maintained while a trench was opened and area cleaned? (YES) (NO)

Time Water Main Valved Off (positive pressure removed) am pm

Nature of Leak or Break

Replaced leaking Blue Max Service

Were State approved or AWWA Standards Followed: (YES) (NO)

Detailed summary of repair procedure used (Use back of page if needed)

Replaced with copper

Was water main contaminated during the repair process? (YES) (NO)

Disinfection Procedure / Calculations (Use back of page if needed) Flushed line

Amount of Time Line Flushed 1 Minutes Ending Chlorine Residual mg/L 2.26

Bacteriological Sample Collected: YES NO Results**

Date Time Water Main Returned to Service am pm

Additional Comments

See Photos

Adam - Bull - Wendell

COPY