

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 12/12/10 Time: 9:00 Pm: Location: 111 Lee Road

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed).

Date Time of Initial Flush:

Chlorine Residual after Flush:

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO 3 Number of Customers Affected

Main Size 2" Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): 6 am pm

Nature of Leak or Break:

2" Couple busted + crack in pipe

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Clean and Bleached

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Parts Clean with Bleach installed in main

Amount of Time Line Flushed: 30 Minutes Ending Chlorine Residual: mg/L

Bacteriological Sample Collected: YES NO Results**

**Attach copy of results to record)

Date Time Water Main Returned to Service: 20 am / pm

Additional Comments:

