

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 11/5/09 Time 4:30 Location 112 West Hills Court

Please Circle Appropriate Action: New Line Installation Line Repair Service Line

NEW LINE INSTALLATION:

COPY

Were State approved or AWWA Standards Followed (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Chlorine Residual Prior to Initial Flush

Date Time of Initial Flush

Length of Time of Initial

Flush

Chlorine Residual after Flush

Water Supply (WS) Project Number

FOR LINE REPAIRS:

Interruption of Water Service YES NO ☒ Number of Customers Affected

Water Size 2" GALV Repaired Under Pressure YES ☒ NO

For partially or fully de-watered mains

Was positive pressure maintained while a trench was opened and area cleaned? (YES) ☒ NO

Time Water Main Valved Off (positive pressure removed) am pm

Nature of Leak or Break

Hole in 2" Galv. Line

Were State approved or AWWA Standards Followed (YES) ☒ NO

Detailed summary of repair procedure used (Use back of page if needed)

Bleach & Clean band and 2" Galv. Line

Is water main contaminated during the repair process? (YES) ☒ NO

Disinfection Procedure Calculations (Use back of page if needed)

Amount of Time Line Flushed

Minutes

Ending Chlorine

Residual mg/L

Bacteriological Sample Collected YES NO

Results**

**Attach copy of results to record

Date Time Water Main Returned to Service

am pm

Additional Comments

