

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 2-11-11 Time 9:15 am Location 117 Walnut St

Please select the Appropriate Action: New Line Installation Line Repair Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed (YES / NO)
Detailed summary of disinfection procedure used (Use back of page if needed)

Monitor Residual Prior to Initial Flush
Date Time of Initial Flush Length of Time of Initial
Flush Chlorine Residual after Flush

Water Supply (WS) Project Number

FOR LINE REPAIRS:

Interruption of Water Service YES NO Number of Customers Affected

Main Size 2" Repaired Under Pressure YES NO

For partially or fully de-watered mains

Was positive pressure maintained while a trench was opened and area cleaned? YES NO

Time Water Main Valved Off (positive pressure removed) am pm

Nature of Leak or Break

pinhole in main line

Were State approved or AWWA Standards Followed (YES / NO)
Detailed summary of repair procedure used (Use back of page if needed)

Was water main contaminated during the repair process? (YES / NO)
Disinfection Procedure Calculations (Use back of page if needed)

Amount of Time Line Flushed	Minutes	Ending Chlorine
Residual mg/L		

Bacteriological Sample Collected YES NO Results**

**Attach copy of results to record

Date Time Water Main Returned to Service am pm

Additional Comments

See Photos

Adam-Daniel-Kim

COPY

2-18-11

8

Y-100