	FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
D	ate: 12-4-13 Time: 10:30-An Location: 122 Jasper Dr
Ρ	lease Circle Appropriate Action: New Line Installation / Line Repair / Service Line
V	Vere State approved or AWWA Standards Followed: (YES/ NO) Detailed summary of disinfection procedure used (Use back of page if needed):
	Chlorine Residual Prior to Initial Flush: Date / Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
1	Nater Supply (WS) Project Number:
-	FOR LINE REPAIRS:
1	nterruption of Water Service: YES NONumber of CustomersAffected:
F	Main Size: Repaired Under Pressure: YES NO
	For partially or fully de-watered mains:
1	Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) ¹ Time Water Main Valved Off (positive pressure removed): am / pm Nature of Leak or Break:
	Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of repair procedure used (Use back of page if needed):
	Was water main contaminated during the repair process? (YES / NO) Disinfection Procedure / Calculations (Use back of page if needed):
	Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
	Bacteriological Sample Collected: YESNO Results**: (**Attach copy of results to record)
	Date / Time Water Main Returned to Service: am / pm
	Additional Comments: Per 07-21-09 Donnie/Billy/Jimny/TJ

.:

V900