FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 85-13 Time: 9:00 m Location: 122 lubsprings
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES) NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: Repaired Under Pressure: YES V NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of repair procedure used (Use back of page if needed):
Was water main contaminated during the repair process? (YES / NO) Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YES NO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments:

Rev 01-21-09

"-To-July 65 MONA [140 A 11]

COPY

the second potential second se

그는 그 그는 그는 그들을 가는 것들을 가는 것들을 하는 것이 되었다.

in the second of the second of