FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 10-5-11 Time: 4:00 Location: 123 Silvelden Crown
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION: Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 4" PUL Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) ¹Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: leaking split service
Were State approved or AWWA Standards Followed: (YES) NO) Replication with Detailed summary of repair procedure used (Use back of page if needed): (OPAC)
Was water main contaminated during the repair process? (YES(NO)) Disinfection Procedure / Calculations (Use back of page if needed): [= losked lence
Amount of Time Line Flushed: Minutes Ending Chlorine 2, 20 Residual: mg/L
Bacteriological Sample Collected: YES NO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Sec Photos
Rev 01:21-09

Adam- Kim. Tim