

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-24-10 Time: 3:00 pm Location: 124 Tidwell Cir

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Service line

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Date: Time of Initial Flush:

Chlorine Residual after Flush

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES / NO Number of Customers Affected: 1

Main Size: 2" PVC Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): am pm

Nature of Leak or Break:

Replace service

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Replace with copper

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Flushed line

Amount of Time Line Flushed: 1 Minutes  
Residual mg/L

Ending Chlorine 2.20

Bacteriological Sample Collected: YES NO

Results\*\*

\*\*Attach copy of results to record

Date: Time Water Main Returned to Service: 20 am pm

Additional Comments

