FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
Date: 1-6-10 Time: 2:00 P.M. Location: 128 Histwood Dr.
Please Circle Appropriate Action: New Line Installation (Line Repair / Service Line
NEW LINE INSTALLATION: Adam / Po
Were State approved or AWWA Standards Followed: (YES / NO)  Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: 2 Galu Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)  1 Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break:  Splitte in 2" Golu
Were State approved or AWWA Standards Followed: (YES NO)  Detailed summary of repair procedure used (Use back of page if needed):  Recalled with band
Was water main contaminated during the repair process? (YES NO)  Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YES NO Results**:  (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: 2' x 3' holc
30 Sec to (cisc 6"

			Ó