	FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
Dat	te: 12-4-13 Time: _1:00 pm Location: 130 Jaspon Dr
Ple	ase Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NE	
Ve De	ere State approved or AWWA Standards Followed: (YES / NO) tailed summary of disinfection procedure used (Use back of page if needed): $12/9/13/2$
Ch Da Flu	Iorine Residual Prior to Initial Flush: Ite / Time of Initial Flush: Length of Time of Initial ush: Chlorine Residual after Flush:
W	ater Supply (WS) Project Number:
FC	DR LINE REPAIRS:
Int	terruption of Water Service: YES NONumber of CustomersAffected:
Ma	ain Size: Repaired Under Pressure: YES NO
Fc	or partially or fully de-watered mains:
	as positive pressure maintained while a trench was opened and area cleaned? (YES / O) O) "ime Water Main Valved Off (positive pressure removed): am / pm ature of Leak or Break:
	lere State approved or AWWA Standards Followed: (YES / NO) etailed summary of repair procedure used (Use back of page if needed):
	/as water main contaminated during the repair process? (YES / NO) isinfection Procedure / Calculations (Use back of page if needed):
	mount of Time Line Flushed: Minutes Ending Chlorine
	acteriological Sample Collected: YES NO Results**: **Attach copy of results to record)
D	ate / Time Water Main Returned to Service: am / pm
А	additional Comments:
R	Donnie/Billy/Jimmy/T-J.

COPY