

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 8-11-14 Time: --- Location: 130 Pleasant View Dr
Dogwood Court

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

COPY

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush: _____

Date / Time of Initial Flush: _____ Length of Time of Initial

Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ☒ NO ☐ Number of Customers Affected: 2

Main Size: 2" Repaired Under Pressure: YES ☐ NO ☒

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES /

NO)

Time Water Main Valved Off (positive pressure removed): 1pm - 2pm am / (pm)

Nature of Leak or Break:

Tied 2" pvc on to 6" pcv

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Was water main contaminated during the repair process? (YES / NO) Bleached fittings
Disinfection Procedure / Calculations (Use back of page if needed): flushed line

Amount of Time Line Flushed: 45 Minutes
Residual: _____ mg/L

Ending Chlorine

Bacteriological Sample Collected: YES ☐ NO ☒
(**Attach copy of results to record)

Results**: _____

Date / Time Water Main Returned to Service: 8-11-14 3:00 am / (pm)

Additional Comments: See photos and Drawing

COPY