

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 8-15-12 Time: _____ Location: 132 + 134 Happy Hollow Rd

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)
Detailed summary of disinfection procedure used (Use back of page if needed):

COPY

8/14/12

Chlorine Residual Prior to Initial Flush: _____
Date / Time of Initial Flush: _____ Length of Time of Initial
Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ☒ NO ☐ Number of Customers Affected: 2

Main Size: 2" PVC Repaired Under Pressure: YES ☐ NO ☐

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) YES

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break: 2 leaking service lines

Were State approved or AWWA Standards Followed: YES / NO) Replaced both
Detailed summary of repair procedure used (Use back of page if needed):

with copper

Was water main contaminated during the repair process? (YES / NO) Flushed lines
Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: 1 Minutes
Residual: _____ mg/L

Ending Chlorine 2.20

Bacteriological Sample Collected: YES ☐ NO ☐
(**Attach copy of results to record)

Results**: _____

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments: 132 service - leaking 6 GPM
134 service - leaking - 8 GPM

See Photos

Adam - Donnic - Brett

COPY