

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-16-10 Time: 4:00p.m. Location: 132 Redwood Dr.

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed).

Date: Time of Initial Flush:

Chlorine Residual after Flush:

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO / Number of Customers Affected 6

Main Size 2" PVC Repaired Under Pressure: YES / NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? YES

Time Water Main Valved Off (positive pressure removed): am / pm

Nature of Leak or Break:

hit with backhoe

Were State approved or AWWA Standards Followed: (YES) NO

Detailed summary of repair procedure used (Use back of page if needed):

Replaced 15" section with knock-on

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Bleached pipe and knock on

Amount of Time Line Flushed: 5 Minutes
Residual mg/L

Ending Chlorine

Bacteriological Sample Collected: YES NO
(* Attach copy of results to record)

Results**

Date - Time Water Main Returned to Service: 20 am / pm

Additional Comments:

Opened faucet outside at 218 Redwood Dr. to let out air if any.
Had water coming out both ends during repair time - Little air in line after repair was made
See Photos

