	FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
	Date: 5-8-14 Time: _11:00 Location: 138 String field
Ũ	Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
0	NEW LINE INSTALLATION:
x	Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
	Chlorine Residual Prior to Initial Flush: Date / Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
	Water Supply (WS) Project Number:
	FOR LINE REPAIRS:
	Interruption of Water Service: YES NONumber of CustomersAffected:
	Main Size: 6 PUC Repaired Under Pressure: YES NO
	For partially or fully de-watered mains:
0	Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) ¹ Time Water Main Valved Off (positive pressure removed): am / pm
	Nature of Leak or Break: (Caking Valuat Service
	Were State approved or AWWA Standards Followed: (YES) NO) Replace Coupling Detailed summary of repair procedure used (Use back of page if needed):
	Was water main contaminated during the repair process? (YES / NO) Flushed line Disinfection Procedure / Calculations (Use back of page if needed):
	Amount of Time Line Flushed: Minutes Ending Chlorine 2.20 Residual: mg/L
	Bacteriological Sample Collected: YESNO Results**: (**Attach copy of results to record)
	Date / Time Water Main Returned to Service: am / pm
Ú	Additional Comments: Adam
	Rev 01-21-09
	Jimy

COPY

가 있는 것 같은 것 같은 것 같은 것 같은 것 같은 것 같이 있다. 1995년 전 1997년 전 1997년 1997년

And a set of the set o