FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR 9-3-10 Time: 7:30 am, Location: 150 Forcet Hills Dr. Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR NEW LINE INSTALLATION: Werk State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed) Chlorine Residual after Flush Date Time of Initial Flush: Water Supply (WS) Project Number: FOR LINE REPAIRS: Number of Customers Affected interpolation of Water Service: YES NO Nam Size 2" PUC Repaired Under Pressure: YES For partially or fully de-watered mains: Was positive pressure maintained while a trench was opened and area cleaned (YE Water Main Valved Off (positive pressure removed): am pm Wallule of Leak or Break hole in top of 2" Puc We'e State approved or AWWA Standards Followed: (YES/NO) Detailed summary of repair procedure used (Use back of page if needed): Repaired with Bend Was water main contaminated during the repair process? (YES / NO) Disinfection Procedure / Calculations (Use back of page if needed) 13 leached Band Amount of Time Line Flushed: Ending Chlorine Minutes Residual mg/L Results" Badteriological Sample Collected: YES NO "Attach copy of results to record)

Additional Comments: Bis Leak from 5 am. to 8 am.

20

30 + gpm.

Date Time Water Main Returned to Service:

Adam - Kin-Billy

am pin