FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

2/
Date: 8-22-13 Time: 9:30 Location: 160 Douler Rd
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed): 8/23/13
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YESNONumber of CustomersAffected:(
Main Size: 2" DUC Repaired Under Pressure: YES NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) Time Water Main Valved Off (positive pressure removed): am / pm
Nature of Leak or Break: leaking plastic sciolic
Were State approved or AWWA Standards Followed: (YES / NO) Replace with Copper Detailed summary of repair procedure used (Use back of page if needed):
Was water main contaminated during the repair process? (YES (NO)) Plushed line Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine 2,20 Residual: mg/L
Bacteriological Sample Collected: YES NO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments: Sec Photos
Rev 01-21-09 Adam Jimry Brett James T
2000