FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR Date 8-1-12 Time: 2:60 Pr. Location: 1660 Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line NEW LINE INSTALLATION: Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed): Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush: Water Supply (WS) Project Number: FOR LINE REPAIRS: Interruption of Water Service: YES NO Number of CustomersAffected: Main Size 2 PUC Repaired Under Pressure: YES NO For partially or fully de-watered mains: Was positive pressure maintained while a trench was opened and area cleaned? (YES / Time Water Main Valved Off (positive pressure removed): am / pm Nature of Leak or Break: Replaced once leaking Sequice line - Blue May Were State approved or AWWA Standards Followed: (YES) NO) Replaced with cooper Detailed summary of repair procedure used (Use back of page if needed): Was water main contaminated during the repair process? (YES (NO) Disinfection Procedure / Calculations (Use back of page if needed): Amount of Time Line Flushed: Minutes Ending Chlorine 2,20 Residual: mg/L

Bacteriological Sample Collected: YES____NO___ Results** (**Attach copy of results to record)

Date / Time Water Main Returned to Service:

Additional Comments: Sec Photos

dan- Bull-Brett Rev 01-21-09

