FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 3-13-13 Time: 9:15 A.M. Location: 178 Forest 71:115
Please Circle Appropriate Action: New Line Installation / Cine Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NO/ Number of CustomersAffected:
Main Size: 2" pvc Repaired Under Pressure: YES V NO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES)/ NO) Time Water Main Valved Off (positive pressure removed):
Nature of Leak or Break
Were State approved or AWWA Standards Followed: (FE9 / NO) Detailed summary of repair procedure used (Use back of page if needed): Bleached Band cleaned pine
Was water main contaminated during the repair process? (YES /NO) Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L
Bacteriological Sample Collected: YESNO Results**:
Date / Time Water Main Returned to Service: am / pm
Additional Comments:
Dom'E, Billy, James T.

COPY