

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 4-13-10 Time: 5:30 AM Location: 196 Snow Ln.

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO) **COPY** 4-21-10
Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush: _____
Date / Time of Initial Flush: _____ Length of Time of Initial
Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ☒ NO ☐ Number of Customers Affected: 3

Main Size: 2" PVC Repaired Under Pressure: YES ☒ NO ☐

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES)
NO)

Time Water Main Valved Off (positive pressure removed): 5:30 am / pm

Nature of Leak or Break:

Broken glue coupling Put 5ft piece of PVC in made new Tap

Were State approved or AWWA Standards Followed: (YES) / NO)
Detailed summary of repair procedure used (Use back of page if needed):

Bleached all parts H₂O 18" around pipe

Was water main contaminated during the repair process? (YES / NO)
Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: _____ Minutes Ending Chlorine
Residual: _____ mg/L

Bacteriological Sample Collected: YES ☐ NO ☐ Results**: _____
(**Attach copy of results to record)

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments:

COPY