

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 10-8-10 Time 2:00 p.m. Location 205 Alice St.

Choose the Appropriate Action: New Line Installation Line Repair Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed (YES NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Chlorine Residual Prior to Initial Flush

Date Time of Initial Flush

Length of Time of Initial

Flush

Chlorine Residual after Flush

Water supply WS: Project Number

FOR LINE REPAIRS:

Interruption of Water Service YES / NO Number of Customers Affected 2

Main Size 3/4 plastic Repaired Under Pressure YES NO

For partially or fully de-watered mains

Was positive pressure maintained while a trench was opened and area cleaned YES

Time Water Main Valved Off (positive pressure removed) am pm

Nature of Leak or Break

Replacing split service - leaking

Were State approved or AWWA Standards Followed (YES NO)

Detailed summary of repair procedure used (Use back of page if needed)

Replaced with copper

Was water main contaminated during the repair process? (YES NO)

Disinfection Procedure Calculations (Use back of page if needed)

Flushed line

Amount of Time Line Flushed
Residual mg/L

3

Minutes

Ending Chlorine 2.20

Bacteriological Sample Collected YES NO

Results**

**Attach copy of results to record

Date Time Water Main Returned to Service

am pm

Additional Comments

Need to replace all the way back to the main
Just replaced 80ft.

